

which affected the Visayas area. A copy of the PAGASA Tropical Cyclone Summary of Typhoon Ursula of 2019, is attached hereto as **Annex "G"**.

12. Due to the intensity of Typhoon "Ursula", and its tail-end effects even upon its exit from PAR, some transmission lines/structures in Visayas Districts 1 and 4 were toppled and broken. Copies of the Consolidated List and Details of Damages to NGCP Assets are attached as **Annexes "H-Series"**.

FME CLAIM

13. After the occurrence of the foregoing, NGCP immediately started the repair, restoration, and rehabilitation of its damaged transmission assets and facilities in order to fully restore transmission service to its customers.
14. In support of its claim for the above described Force Majeure Events, NGCP is submitting the following:

Earthquakes in Mindanao

- a. Consolidated Details of Expenditures for Force Majeure Earthquake Incident in Mindanao (31 October 2019), District 6-MOM, as **Annex "I"**;
- b. Before and After Rehabilitation Pictures of Affected Assets FME Earthquake at District 6-MOM, as **Annex "J"**;
- c. Consolidated Details of Expenditures for Force Majeure Earthquake Incidents in Mindanao (15 December 2019 and 31 January 2020), District 5-MOM, as **Annex "K"**;
- d. Before and After Rehabilitation Pictures of Affected Assets FME Earthquake (15 December 2019) at District 5-MOM, as **Annex "L"**; and
- e. Before and After Rehabilitation Pictures of Affected Assets FME Earthquake (31 January 2020) at District 5-MOM, as **Annex "M"**.

Typhoon "Tisoy"

- a. Consolidated Details & Charging of Activities and Expenditures for Force Majeure Event Typhoon Tisoy, LSO, as **Annex "N"**;
- b. Before and After Rehabilitation Pictures of Affected Assets FME Typhoon Tisoy – LSO, as **Annex "O"**;
- c. Consolidated Details of Expenditures for Force Majeure Event Typhoon Tisoy, District 2-SLOM, as **Annex "P"**;